

CATERPILLAR 311-A

9LJ / XEBP7213


Contents

Section	Page
Hydraulic system	2

5Q-3558 TRACK GP-500MM

5Q3558 TRACK GP-500MM (20IN.) - 2 REQUIRED S/N 9LJ1-Up 4I7479-Page 2

Drawing 1 of 1




Ref.	Part number	Description	Qty	Code	Group page
1	5Q-3555	SHOE AS (20 Links)	1		
2	5Q-3556	SHOE AS (21 Links)	1		
3	4I-7479	LINK AS-TRACK	1	Y	
4	4I-7538	BOLT-TRACK (46mm LONG)	164		
5	5I-6125	NUT-TRACK	164		
6	8T-4139	BOLT (30mm LONG)	8		
7	5Q-3588	BUSHING	8		
THE FOLLOWING SERVICE REPAIR IS AVAILABLE:					
8	5Q-3621	SHOE	1	A	

CAT codes: A, Y.

4I-7479 LINK AS-TRACK

4I7479 LINK AS-TRACK S/N 9LJ1-Up Part of 5Q3558 Track listed on Page 1

Drawing 1 of 1




Ref.	Part number	Description	Qty	Code	Group page
1	4I-7475	LINK	40		
2	095-0863	COTTER	1		
3	4I-7477	LINK	1		
4	093-1887	BUSHING	1		
5	4I-7478	LINK	1		
6	099-0653	PIN	1		
7	093-0037	SPACER	2		
8	4I-7476	LINK	40		
9	5I-6140	PIN	40		
10	4I-7473	SEAL	80		
11	6I-6446	BUSHING	40		

SERVICE INSTRUCTION

SERVICE INSTRUCTION

Drawing 1 of 1



Ref.	Part number	Description	Qty	Code	Group page
Parts list rows are not synced on this VPS for XEBP7213/XEBP72130005 yet.					

MANUALS-KOMATSU.COM

Complete Caterpillar PDF Parts Catalogue

9LJ-XEBP7213

\$99

Buy on this catalogue page in our store.

Download instructions are sent after payment confirmation.

Buy complete PDF - \$99