

CATERPILLAR PIN GRAB

MCE / SEBP4308


Contents

Section	Page
Hydraulic system	2
Basic engine	3
Basic engine	5

274-5997 CYLINDER GP-HYDRAULIC

274-5997 CYLINDER GP-HYDRAULIC S/N PGA1-UP; PGC1-UP; MCE1-UP PART OF 260-1966, 265-7513, 297-6983
COUPLER GP-QUICK

Drawing 1 of 1




Ref.	Part number	Description	Qty	Code	Group page
1	091-5928	FITTING-GREASE	2		
2	172-8406	VALVE GP-CHECK (HYD CYLINDER, QUICK COUPLER)	1		
	2U-5338	SEAL-O-RING	1		
	9W-3340	SEAL-O-RING	1		
	107-7640	SEAL-O-RING	1		
AVAILABLE REPAIR KIT(S):					
	252-5507	KIT-SEAL (COUPLER CYLINDER)	1		

297-6983 COUPLER GP-QUICK

297-6983 COUPLER GP-QUICK S/N MCE1-UP PART OF 307-2941, 318-8207 COUPLER AR-QUICK

Drawing 1 of 1



Ref.	Part number	Description	Qty	Code	Group page
1	274-5997	CYLINDER GP-HYDRAULIC	1	Y	
2	274-5995	HOOK	1		
3	274-5992	PIN	1		
4	274-5993	PIN	1		
5	274-5994	PIN	1		
6	3B-8489	FITTING-GREASE (1/8-27 PTF)	4		
7	275-0497	SPRING (INCLUDES BOLTS, WASHERS)	1		
8	171-5956	BEARING	1		
9	274-5999	BAR	1		
10	274-5998	BAR	1		
11	4I-9426	RING-RETAINING	2		

297-6983 COUPLER GP-QUICK (continued)

Ref.	Part number	Description	Qty	Code	Group page
12	274-6001	CLIP	4		
13	273-4159	PLATE-RETAINING	1		
14	118-4140	SCREW (M5X0.8X19-MM)	2	M	

CAT codes: M, Y.

307-2941 COUPLER AR-QUICK

307-2941 COUPLER AR-QUICK S/N MCE1-UP FOR USE WITH 325C EXCAVATOR WITH "C" AND "CB" LINKAGE

Arrangement composition. Follow the table links to the component drawings.

Ref.	Part number	Description	Qty	Code	Group page
	297-6983	COUPLER GP-QUICK	1	Y	3
	7Y-5227	BOLT (M16X2X190-MM)	2	M	
	268-4531	FILM-INSTRUCTION (COUPLER OPERATION)	1		
	268-4530	FILM-WARNING (CRUSH HAZARD, READ OMM, U.S.)	1		
	268-8872	FILM-WARNING (CRUSH HAZARD, READ OMM, U.S.)	1		
	8T-4132	NUT (M16X2-THD)	4	M	
	7Y-2357	PIN	2		
	160-8290	SHIM (1-MM THK)	2		

CAT codes: M, Y.

318-8207 COUPLER AR-QUICK

318-8207 COUPLER AR-QUICK S/N MCE1-UP FOR USE WITH 325B EXCAVATOR WITH "C" AND "CB" LINKAGE

Arrangement composition. Follow the table links to the component drawings.

Ref.	Part number	Description	Qty	Code	Group page
	297-6983	COUPLER GP-QUICK	1	Y	3
	268-4531	FILM-INSTRUCTION (COUPLER OPERATION)	1		
	268-4530	FILM-WARNING (CRUSH HAZARD, READ OMM, U.S.)	1		
	268-8872	FILM-WARNING (CRUSH HAZARD, READ OMM, U.S.)	1		
	160-8290	SHIM (1-MM THK)	2		

CAT codes: Y.

MANUALS-KOMATSU.COM

Complete Caterpillar PDF Parts Catalogue

MCE-SEBP4308

\$99

Buy on this catalogue page in our store.

Download instructions are sent after payment confirmation.

Buy complete PDF - \$99