





PWF3100

Reference: E4110-01A0

## 030010 Battery

| Item | Part No.     | Part Name                               | Qty | Options       |
|------|--------------|-----------------------------------------|-----|---------------|
| 1    | 37A-2D5-1010 | BATTERY ASSEMBLY, (SHIN-KOBE 48V-330AH) | 1   | SN: 805001-UP |
|      | 37A-2D5-1020 | BATTERY ASSEMBLY, (SHIN-KOBE 48V-400AH) | 1   | SN: 805001-UP |
|      | 37A-2D5-1030 | BATTERY ASSEMBLY, (SHIN-KOBE 48V-485AH) | 1   | SN: 805001-UP |
|      | 37A-2D5-1040 | BATTERY ASSEMBLY, (SHIN-KOBE 48V-545AH) | 1   | SN: 805001-UP |
|      | 37A-2D6-1040 | BATTERY ASSEMBLY, (GS 48V-545AH)        | 1   | SN: 805001-UP |
|      | 37B-2D6-1040 | BATTERY ASSEMBLY, (GS 48V-700AH)        | 1   | SN: 805001-UP |
| 2    | 3EB-50-31130 | CUSHION                                 | 3   | SN: 805001-UP |
| 3    | 01580-10806  | NAT                                     | 3   | SN: 805001-UP |
| 4    | 01640-20816  | WASHER                                  | 3   | SN: 805001-UP |

Reference: E4110-01A0



PJF8114


Reference: F4130-01A0

## 060010 POWER TRAIN (CASE)

| Item | Part No.     | Part Name             | Qty | Options       |
|------|--------------|-----------------------|-----|---------------|
| 1    | 3BA-21-56110 | CASE ASSEMBLY         | 1   | SN: 805001-UP |
|      | 3BA-21-57110 | CASE ASSEMBLY, (COLD) | 1   | SN: 805001-UP |
| 2    | 3BA-21-56140 | CASE ASSEMBLY         | 1   | SN: 805001-UP |
|      | 3BA-21-57140 | CASE ASSEMBLY, (COLD) | 1   | SN: 805001-UP |
| 3    | 01010-81240  | BOLT                  | 13  | SN: 805001-UP |
| 4    | 01010-81280  | BOLT                  | 1   | SN: 805001-UP |
| 5    | 01643-31232  | WASHER                | 16  | SN: 805001-UP |
| 6    | 01010-81255  | BOLT                  | 1   | SN: 805001-UP |
| 7    | 01010-81250  | BOLT                  | 1   | SN: 805001-UP |
| 8    | 04020-01228  | PIN, DOWEL            | 2   | SN: 805001-UP |
| 9    | 3BA-21-56430 | GASKET (KIT)          | 1   | SN: 805001-UP |
| 10   | 01050-51480  | BOLT                  | 5   | SN: 805001-UP |
| 11   | 01643-31445  | WASHER                | 5   | SN: 805001-UP |
| 12   | 3EB-21-15211 | CAP                   | 1   | SN: 805001-UP |
| 13   | 34B-41-12910 | PLUG (KIT)            | 1   | SN: 805001-UP |
| 14   | 34B-41-12920 | GASKET (KIT)          | 1   | SN: 805001-UP |
| 15   | 07042-20312  | PLUG                  | 1   | SN: 805001-UP |
| 16   | 06000-06306  | BEARING               | 1   | SN: 805001-UP |
| 17   | 06000-06009  | BEARING               | 1   | SN: 805001-UP |
| 18   | 07000-02090  | O RING                | 1   | SN: 805001-UP |
| 19   | 3BA-21-13140 | CAP                   | 1   | SN: 805001-UP |
| 20   | 04065-09030  | RING, SNAP            | 1   | SN: 805001-UP |
| 21   | 06000-06308  | BEARING               | 2   | SN: 805001-UP |
| 22   | 3BA-21-41370 | BEARING               | 1   | SN: 805001-UP |
| 23   | 3BB-21-31380 | BEARING               | 1   | SN: 805001-UP |
| 24   | 3BB-21-31410 | GAUGE                 | 1   | SN: 805001-UP |
| 25   | 01010-81240  | BOLT                  | 3   | SN: 805001-UP |
| 26   | 01643-31232  | WASHER                | 3   | SN: 805001-UP |
| 27   | 3EB-14-11220 | PLATE                 | 1   | SN: 805001-UP |
| 28   | 01010-80825  | BOLT                  | 2   | SN: 805001-UP |
| 29   | 07000-02080  | O RING                | 1   | SN: 805001-UP |
| 30   | 04064-03015  | RING, SNAP            | 1   | SN: 805001-UP |
| 31   | 3EA-21-11151 | BOLT                  | 12  | SN: 805001-UP |
|      |              | SERVICE KIT           |     |               |

| Item | Part No.     | Part Name  | Qty | Options       |
|------|--------------|------------|-----|---------------|
| KIT  | 3BA-21-05021 | GASKET KIT | 1   | SN: 805001-UP |

Reference: F4130-01A0



PTF3102


Reference: F4130-02A0

## 060020 POWER TRAIN (GEAR)

| Item | Part No.       | Part Name             | Qty | Options       |
|------|----------------|-----------------------|-----|---------------|
|      | 3BA-21-51311   | DIFFERENTIAL ASSEMBLY | 1   | SN: 805001-UP |
| 1    | 3BA-21-41310   | • CASE                | 1   | SN: 805001-UP |
| 2    | 34A-21-11320   | • BOLT                | 1   | SN: 805001-UP |
| 3    | 3EA-21-11121   | • GEAR                | 2   | SN: 805001-UP |
| 4    | 34A-21-11141   | • BUSH                | 2   | SN: 805001-UP |
| 5    | 300-22-31450   | • PIN                 | 1   | SN: 805001-UP |
| 6    | 3BA-21-51321   | • GEAR                | 2   | SN: 805001-UP |
| 7    | 34A-21-11131   | • BUSH                | 2   | SN: 805001-UP |
| 8    | 06000-06311    | BEARING               | 2   | SN: 805001-UP |
| 9    | 01050-81025    | BOLT                  | 16  | SN: 805001-UP |
| 10   | 06000-30212    | BEARING               | 2   | SN: 805001-UP |
| 11   | 3EA-21-14131   | SEAL (KIT)            | 2   | SN: 805001-UP |
| 12   | 01010-80612    | BOLT                  | 2   | SN: 805001-UP |
| 13   | 3BA-21-51331   | SHAFT                 | 2   | SN: 805001-UP |
| 14   | 3BA-21-41220   | BEARING               | 2   | SN: 805001-UP |
| 15   | 3BA-21-41440   | SEAL (KIT)            | 2   | SN: 805001-UP |
| 16   | 3BA-21-41150   | NAT                   | 2   | SN: 805001-UP |
| 17   | 3BA-21-41160   | PLATE                 | 2   | SN: 805001-UP |
| 18   | 3BA-21-51171   | SUPPORT, RIGHT        | 1   | SN: 805001-UP |
|      | 3BA-21-51171WA | SUPPORT, RIGHT (COLD) | 1   | SN: 805001-UP |
| 19   | 3EA-21-32190   | O RING                | 1   | SN: 805001-UP |
| 20   | 07020-00001    | FITTING, GREASE       | 1   | SN: 805001-UP |
| 21   | 01010-81865    | BOLT                  | 8   | SN: 805001-UP |
| 22   | 01643-31845    | WASHER                | 8   | SN: 805001-UP |
| 23   | 01580-11815    | NAT                   | 4   | SN: 805001-UP |
| 24   | 3BA-21-56510   | GEAR                  | 1   | SN: 805001-UP |
| 25   | 3BA-21-56330   | GEAR                  | 1   | SN: 805001-UP |
| 26   | 3BA-21-56340   | SHAFT ASSEMBLY        | 1   | SN: 805001-UP |
| 27   | 3BA-21-51211   | GEAR                  | 1   | SN: 805001-UP |
| 28   | 3BA-21-41141   | HUB                   | 2   | SN: 805001-UP |
|      | 3BA-21-41141WA | HUB, (COLD)           | 2   | SN: 805001-UP |
| 29   | 3EA-21-14121   | BOLT                  | 16  | SN: 805001-UP |
| 30   | 3BA-55-51740   | BRACKET               | 1   | SN: 805001-UP |
|      |                | SERVICE KIT           |     |               |

| Item | Part No.     | Part Name | Qty | Options       |
|------|--------------|-----------|-----|---------------|
| KIT  | 3BA-21-05010 | SEAL KIT  | 2   | SN: 805001-UP |

Reference: F4130-02A0




PJF8115

Reference: G4110-01A0

## 090010 TRACTION MOTOR

| Item | Part No.     | Part Name      | Qty | Options       |
|------|--------------|----------------|-----|---------------|
| 1    | 3BA-17-56111 | MOTOR ASSEMBLY | 1   | SN: 805001-UP |

Reference: G4110-01A0



PJF6149


Reference: G4110-51A0

## 090020 TRACTION MOTOR (INNER PARTS)

| Item | Part No.       | Part Name        | Qty | Options       |
|------|----------------|------------------|-----|---------------|
|      | 3BA-17-56111   | MOTOR ASSEMBLY   | 1   | SN: 805001-UP |
| 1    | FBNABRE3134KLZ | • FRAME ASSEMBLY | 1   | SN: 805001-UP |
| 2    |                | • ☆ STATOR       | 1   | SN: 805001-UP |
| 3    |                | • ☆ CABLE        | 3   | SN: 805001-UP |
| 4    |                | • ☆ SENSOR       | 1   | SN: 805001-UP |
| 5    |                | • ☆ GROMMET      | 1   | SN: 805001-UP |
| 6    | FBDN-9463A     | • ROTOR          | 1   | SN: 805001-UP |
| 7    |                | • ☆ SHAFT        | 1   | SN: 805001-UP |
| 8    | FBNBARE3110LCZ | • BRACKET, FRONT | 1   | SN: 805001-UP |
| 9    | FBNBARB3307LDR | • BRACKET, REAR  | 1   | SN: 805001-UP |
| 10   | FB6207LLU      | • BEARING        | 1   | SN: 805001-UP |
| 11   | FB6305LLU      | • BEARING        | 1   | SN: 805001-UP |
| 12   | FBNBFRA4204KJZ | • GUIDE          | 1   | SN: 805001-UP |
| 13   | FBSC-305011    | • SEAL, OIL      | 1   | SN: 805001-UP |
| 14   | FBNPHRA4068HAZ | • GEAR, SENSOR   | 2   | SN: 805001-UP |
| 15   | FBML-6619      | • SENSOR         | 2   | SN: 805001-UP |
| 16   | FBJISB2804-S20 | • RING, SNAP     | 1   | SN: 805001-UP |
| 17   | FBNBZRZ4243ZZZ | • COVER, SENSOR  | 1   | SN: 805001-UP |
| 18   | FB1S10X260     | • BOLT           | 4   | SN: 805001-UP |
| 19   | FBBWW-6306     | • WASHER         | 1   | SN: 805001-UP |
| 20   | FBBWW-6001     | • WASHER         | 2   | SN: 805001-UP |
| 21   | FBAPBTP-2-6X16 | • BOLT           | 2   | SN: 805001-UP |
| 22   | FB4621-8       | • EYE BOLT       | 1   | SN: 805001-UP |
| 23   | FBNGFRA4055P1Z | • GROMMET        | 3   | SN: 805001-UP |
| 24   | FB1P-M8X43M-U  | • TERMINAL       | 3   | SN: 805001-UP |
| 25   | FB4211S-8      | • NAT            | 9   | SN: 805001-UP |
| 26   | FB4242S-8      | • WASHER         | 9   | SN: 805001-UP |
| 27   | FB4251S-8      | • WASHER         | 3   | SN: 805001-UP |
| 28   | FBNGZRZ4265ZZD | • BRACKET        | 1   | SN: 805001-UP |

Catalog signs: ☆ not supplied separately: assembly only

Reference: G4110-51A0




PTFS104

Reference: G4130-01A0

## 090030 PUMP MOTOR

| Item | Part No.     | Part Name           | Qty | Options       |
|------|--------------|---------------------|-----|---------------|
| 1    | 3BA-18-51110 | PUMP MOTOR ASSEMBLY | 1   | SN: 805001-UP |

Reference: G4130-01A0




PTF3263

Reference: G4130-51A0

## 090040 PUMP MOTOR (INNER PARTS)

| Item | Part No.       | Part Name               | Qty | Options       |
|------|----------------|-------------------------|-----|---------------|
|      | 3BA-18-51110   | PUMP MOTOR ASSEMBLY     | 1   | SN: 805001-UP |
| 1    | FB0-51100-2160 | • ARMATURE ASSEMBLY     | 1   | SN: 805001-UP |
| 2    | FB1-0454-62057 | • BEARING, BALL         | 1   | SN: 805001-UP |
| 3    | FB1-0454-62067 | • BEARING, BALL         | 1   | SN: 805001-UP |
| 4    | FB0-51230-2140 | • FIELD COIL ASSEMBLY   | 1   | SN: 805001-UP |
| 5    | FB0-51787-0030 | • TERMINAL              | 2   | SN: 805001-UP |
| 6    | FB0-51311-1900 | • FRONT BRACKET         | 1   | SN: 805001-UP |
| 7    | FB0-0270-06552 | • BOLT                  | 4   | SN: 805001-UP |
| 8    | FB1-51420-0120 | • FAN ASSEMBLY          | 1   | SN: 805001-UP |
|      | FB0-51700-2030 | • REAR BRACKET ASSEMBLY | 1   | SN: 805001-UP |
| 9    | FB0-51711-1720 | •• REAR BRACKET         | 1   | SN: 805001-UP |
| 10   | FB0-51730-0540 | •• HOLDER RING ASSEMBLY | 1   | SN: 805001-UP |
| 11   | FB0-09001-5300 | •• BOLT                 | 4   | SN: 805001-UP |
| 12   | FB0-51913-0320 | •• SPRING, BRUSH        | 4   | SN: 805001-UP |
| 13   | FB0-51740-0650 | •• BRUSH                | 4   | SN: 805001-UP |
| 14   | FB0-0080-06752 | •• BOLT                 | 4   | SN: 805001-UP |
| 15   | FB0-51810-0800 | •• BAND ASSEMBLY        | 1   | SN: 805001-UP |
| 16   | FB1-31921-0121 | •• WASHER               | 2   | SN: 805001-UP |

Reference: G4130-51A0



PTF3105

Reference: G4140-01A0

090050 PUMP MOTOR INSTALLATION PARTS

| Item | Part No.       | Part Name | Qty | Options       |
|------|----------------|-----------|-----|---------------|
| 1    | 3BA-18-51510SA | BRACKET   | 1   | SN: 805001-UP |
| 2    | 01010-81025    | BOLT      | 3   | SN: 805001-UP |
| 3    | 01643-31032    | WASHER    | 3   | SN: 805001-UP |
| 4    | 3BB-18-21220   | CUSHION   | 8   | SN: 805001-UP |
| 5    | 3BB-18-21231SA | PIPE      | 4   | SN: 805001-UP |
| 6    | 01010-81045    | BOLT      | 4   | SN: 805001-UP |
| 7    | 01643-31845    | WASHER    | 4   | SN: 805001-UP |
| 8    | 01643-31032    | WASHER    | 4   | SN: 805001-UP |

Reference: G4140-01A0

# Get the complete PDF catalogue

Komatsu FB15EXGF-10 (JPN) Battery Forklift-Counter-Balance Type S/N 805001-807000  
(Japanese)

**\$89**

with PayPal | Store cart: \$99

**Buy this PDF on Manuals Komatsu**

Check the model, serial range and language before payment.  
Download instructions are emailed after payment confirmation.

This free sample contains 10 catalogue pages.